

Li	9,50E-07
Be	9,60E-07
B	5,40E-07
C	4,60E-06
N	3,20E-07
O	3,80E-07
F	8,00E-08
Na	1,90E-06
Mg	2,10E-06
Al	4,20E-06
Si	3,90E-06
P	5,00E-08
S	7,20E-06
Cl	5,90E-07
K	2,40E-07
Y	5,00E-08
Zr	1,10E-07
Nb	1,90E-07
Mo	2,10E-07
Ru	1,30E-07
Rh	9,00E-08
Pd	2,20E-07
Ag	8,70E-06
In	4,30E-06
Sn	2,40E-06
Sb	2,60E-07
Zn	7,20E-06
I	5,00E-08
Cs	1,00E-07
Ba	9,80E-07
Ce	5,00E-08
Pr	5,00E-08
Nd	1,00E-07
Sm	1,00E-07
Eu	1,00E-07
Gd	1,00E-07
Tb	1,00E-07
Dy	1,00E-07
Ho	1,00E-07
Er	1,00E-07
Tm	1,00E-07
Yb	1,00E-07
Lu	1,00E-07
Hf	1,00E-07
W	3,60E-06
Os	1,00E-07
Ir	1,00E-07
Pt	1,40E-06
Au	5,20E-07
Hg	2,30E-06
Tl	5,90E-06
Pb	9,10E-06
Bi	1,10E-06
Th	1,00E-07
U	5,00E-08
Ca	9,90E-06

Rb	2,10E-07
La	8,70E-07
Re	1,20E-06
Total	9,08E-05 at. %